





Sleepy Hollow Park



<p>Sleepy Hollow Park is a large sized natural are that provides a trail and a bench. The main issues at this park are no accessible route, no accessible surface, no trailhead signage and no companion seating at the park. Please Note: When a UD is indicated, this is a Universal Design (UD) recommendation to enhance accessibility. The UD recommendation is not required to meet the minimum accessibility standards but it would be encouraged. If used in this report, the letters, AFF stand for above finished floor.</p>								
<p>The report uses two different accessibility codes. The 2010 Americans with Disabilities Act Accessibility Guidelines (ADAAG) can be down loaded from the Access Board website. The website is www.access-board.gov. In addition, the Illinois Accessibility Code (IAC) was also used in this report. This code can be down loaded from the website, www.cbd.state.il.us/IAC. The estimated costs for correction of access barriers are taken from the "Means ADA Compliance Pricing Guide 2nd Edition". Each estimated costs for corrective actions have been adjusted for inflation and regional costs to better reflect the 2024 expenses in the suburban Chicagoland area.</p>								
<p>The Elmhurst Park District is part of a local government which requires compliance with Title II of the Americans with Disabilities Act (ADA). Changes to the Park District would allow for equal opportunity to participate in programs and activities, effective communication, and program accessibility. Access of programs and activities can be achieved by removal of physical barriers, modification of policies, practices and procedures that discriminate against a person with a disability and relocation to an accessibility facility. In existing facilities, the ADA does allow the relocation of a program from an inaccessible facility to an accessible facility until all access barriers have been removed. See 28 C.F.R. §35.150(a)(1);(b)(1) for additional information.</p>								
<p>PLEASE NOTE: In existing facilities, the ADA does allow the relocation of a program from an inaccessible facility to an accessible facility until all access barriers have been removed. See 28 C.F.R. §35.150(a)(1);(b)(1) for additional information. ADAAG 206.2 requires that at least one accessible route be provided within the boundary of the site. The reports provide comments on all routes that when upgrades are made in the future modifications can be made to correct the access barrier or in some cases modify to the greatest extent possible.</p>								
Photo	Barrier	ADAAG/IAC	Solution	Priority	By Whom	Projected Cost	Projected Date	Action Taken
	No accessible route is provided to the trail for 65 feet.	ADAAG 403	Provide a new accessible route with a running slope no steeper than 5% and a cross slope no steeper than 2%.	1		\$ 2,900.00		

Sleepy Hollow Park



Photo	Barrier	ADAAG/IAC	Solution	Priority	By Whom	Projected Cost	Projected Date	Action Taken
	No accessible surface is provided for the trail for 665 feet.	IAC 1017.2	If using concrete, asphalt or boards then the cross slope can be no steeper than 2%, any other surface can go up to 5%. Other possible trail surfaces can be used such as a 3/4 inches minus limestone with a 50% mix of dust that is firm and stable with a slope no steeper than 2% for a cross slope and no steeper than 5% for a running slope. Provide this surface at the benches, trash cans and signs along the way.	2		\$ 13,300.00		
	No trailhead sign is provided at either side of the trail.	IAC 1017.10	Provide a trailhead sign that includes information on 1) the length of the trail or trail segment, 2) Surface type, 3) Typical and minimum tread width, 4) Typical and maximum running slope, 5) and typical and maximum cross slope.	2		\$ 310.00		
	No companion seating is provided at the bench.	IAC 1011.2.1	Provide a clear ground space of at least 36 inches by 48 inches positioned near the bench with one side adjoining the walkway. The clear ground space should have a slope no steeper than 2% in all directions. The clear ground space should not overlap the accessible route or another clear ground space.	2		\$ 375.00		

Estimated Total Cost for Accessibility Upgrades at Sleepy Hollow Park \$ 16,885.00