## **Kiwanis Park**



Kiwanis Park is a small sized neighborhood park that provides walkways, dog waste bags and benches. The main issues at this park are walkways are in poor condition, benches do not provide companion seating, and a gap is too wide. **Please Note**: When a **UD** is indicated, this is a Universal Design **(UD)** recommendation to enhance accessibility. The **UD** recommendation is not required to meet the minimum accessibility standards but it would be encouraged. If used in this report, the letters, **AFF** stand for above finished floor.

The report uses two different accessibility codes. The 2010 Americans with Disabilities Act Accessibility Guidelines (ADAAG) can be down loaded from the Access Board website. The website is www.access-board.gov. In addition, the Illinois Accessibility Code (IAC) was also used in this report. This code can be down loaded from the website, www.cbd.state.il.us/IAC. The estimated costs for correction of access barriers are taken from the "Means ADA Compliance Pricing Guide 2nd Edition". Each estimated costs for corrective actions have been adjusted for inflation and regional costs to better reflect the 2024 expenses in the suburban Chicagoland area.

The Elmhurst Park District is part of a local government which requires compliance with Title II of the Americans with Disabilities Act (ADA). Changes to the Park District would allow for equal opportunity to participate in programs and activities, effective communication, and program accessibility. Access of programs and activities can be achieved by removal of physical barriers, modification of policies, practices and procedures that discriminate against a person with a disability and relocation to an accessibility facility. In existing facilities, the ADA does allow the relocation of a program from an inaccessible facility to an accessible facility until all access barriers have been removed. See 28 C.F.R. §35.150(a)(1);(b)(1) for additional information.

PLEASE NOTE: In existing facilities, the ADA does allow the relocation of a program from an inaccessible facility to an accessible facility until all access barriers have been removed. See 28 C.F.R. §35.150(a)(1);(b)(1) for additional information. ADAAG 206.2 requires that at least one accessible route be provided within the boundary of the site. The reports provide comments on all routes that when upgrades are made in the future modifications can be made to correct the access barrier or in some cases modify to the greatest extent possible.

Photo	Barrier	ADAAG/IAC	Solution	Priority	By Whom	Projected Cost	Projected Date	Action Taken
送金	The walkway by the dog waste bags is uneven and broken for 26 feet.	ADAAG 302	Provide a surface that is firm, stable and slip resistant and not more than 2% in all directions.	1		\$ 1,150.00		

## **Kiwanis Park**



Photo	Barrier	ADAAG/IAC	Solution	Priority	By Whom	Projected Cost	Projected Date	Action Taken
	Four benches are provided but none of them provide companion seating space.		Provide a clear ground space of at least 36 inches by 48 inches positioned near the bench with one side adjoining the walkway. The clear ground space should have a slope no steeper than 2% in all directions. The clear ground space should not overlap the accessible route or another clear ground space.	2		\$ 375.00		
	A gap at the walkway and sidewalk is too wide at 1 1/2 inches.	ADAAG 302.3	Fill in or replace section of asphalt walkway to provide a flush transition or an opening no greater than 1/2 inch.	1		\$ 220.00		

## **Kiwanis Park**



Photo	Barrier	ADAAG/IAC	Solution	Priority	By Whom	Projected Cost	Projected Date	Action Taken
	The east walkway is in poor condition for 107 feet.	ADAAG 302	Provide a surface that is firm, stable and slip resistant and not more than 2% in all directions.			\$ 4,700.00		
Estimated Total Cost for Accessibility Ungrades at Kiwanis Bark \$ 6.445.00								

Estimated Total Cost for Accessibility Upgrades at Kiwanis Park